


SpeedBox 1.0 for Bosch (Smart System)

Step 1: Preparation for installation


- A. Prepare the following tools: Hex Key H4
- B. Turn off the e-bike.
- C. Remove the battery from the e-bike according to the manufacturer's manual.






Step 2: Motor cover removal

- A. Unscrew the screw holding the motor cover with the hex key H4.
- B. Remove the motor cover.



Step 3: Disconnecting the connectors from the motor


- A. Disconnect the speed sensor connector.
- B. Disconnect the display connector in the same manner.





Step 4: SpeedBox tuning installation


- A. Replace the original connectors with the SpeedBox connectors.
- B. Plug the e-bike connectors, disconnected from the motor (step 3), into the SpeedBox connectors. Make sure that the locks on the connectors are seated properly.
- C. Before assembling the motor, check the correct wiring as shown in the figure.





Step 5: Motor cover assembly

- A. Fit the SpeedBox and all connectors and wires leading from the motor into the free space in the motor.
- B. Place the motor cover back to its original position.
- C. Reattach the motor cover by tightening the screw with the hex key H4.






Step 6: Tuning function check

- A. Place the battery back into the e-bike.
- B. Turn the e-bike on.

E.

- C. Before the first ride with SpeedBox installed, it is necessary to enter the menu and check the wheel circumference: "Settings" > "My Bike" > "Wheel circumference". Then return to the home screen.
- D. Activate/deactivate tuning by brief activation of the WALK function or by switching between two assistance modes twice (+-+-). The value of 9.9 or 2.5 indicating themaximum speed will be displayed.
- E. Spin the rear wheel and make sure the rear wheel speed is shown on the e-bike display.







www.speedbox-tuning.en

Ebike Electronic s.r.o. Rybna 716/24 | 110 00 Praha 1 | Czech Republic | ID: 05553555 | VAT: CZ05553555







